

ThunderMaster Release Note (2018/06/11)

v3.10

Update save BIOS function (nvflash v5.469.0)

v3.9

Update save BIOS function (nvflash v5.449.0)

v3.8

Fixed GTX 1060 5GB issue with new driver (R390)

v3.7

1. Update save BIOS function (nvflash v5.427.0) to support GTX 1060 5GB
2. Fixed temperature display format

v3.6

Add GTX 1070 Ti STD edition in OC/Gaming/Silence mode support list

v3.4

Update save BIOS function (nvflash v5.412.0) to support GTX 1070 Ti

v3.3

Fix P106-100/P104-100 detecting issue.

v3.2

1. Update NVAPI R384
2. Update save BIOS function (nvflash v5.398.0)
3. Added a dialog message to indicate when 'debug mode' option enabled in NV control panel

v3.1

Support 8 GPUs

v3.0

1. Add OC/Gaming/Silence mode tooltip
2. Fix reload OC/Gaming/Silence mode on startup
3. Reduce application size

v2.27

1. Add OC/Gaming/Silence mode (GTX 1080 Ti only)
2. Update save BIOS function (nvflash v5.370.0)

v2.26

Update save BIOS function (nvflash v5.367.0) to support GTX 1080 Ti

v2.25

1. Update save BIOS function (nvflash v5.353.0)
2. Fix status fan curve (fan line response incorrectly)

v2.24

1. Support 6 GPUs
2. Update save BIOS function (nvflash v5.328.0) to support GTX 1060 GP104-140 GPU
3. Fix user mode save issue (can't save fan setting)

v2.23

Update save BIOS function (nvflash v5.323.0) to support GTX 1050 Ti

v2.22

Fix LED control issue (some customer report LED button disappear)

Update G-Panel utility to v1.3

Update save BIOS function to support new GTX 10 series GPU (1060-3G)

Adjust STATUS core clock scale range

v2.21

Fix LED control issue (settings being reset if close the LED control page)

Add Temperature target control.

Fix GPU over voltage setting unsaved.

Update save BIOS function to support new GTX 10 series GPU (1060-6G)

v2.20

Fix LED control issue (settings being reset if close the LED control page)

v2.19

LED Control add "NVIDIA control" for PCB B version of GTX 1080 and GTX 1080 (GameRock and Jetstream series)